

Product Safety Recall



Automated Sliding Gate Opener Motor

Richmond Wheel & Castor Model GTR156

BUNNINGS AND RICHMOND WHEEL & CASTOR CO., BETWEEN 1/07/2020 AND 30/09/2022

IDENTIFICATION:

The gate motor assembly is mounted on a metal frame and has a plastic housing covering the motor and electrical components.

This recall does not affect any other models.

DEFECT:

The main supply cord may be incorrectly wired to the power terminal block.

HAZARD:

Risk of electrical shock causing serious injury or death.

ACTION REQUIRED:

Consumers should open their gate and immediately discontinue use of the automated opener and unplug the gate from the power supply. Consumers should visit the Richmond Wheel & Castor website to download instructions on how to operate the gate manually and what steps to take to confirm if their gate is affected.

Consumers should visit our [website](#) to access instructions.

phone: 0800 61 71 81

email: gatesupport@richmondnz.co.nz

online: <https://www.richmondau.com/gtr156-safety-check/>

New Zealand Importer/Distributor

Richmond Wheel & Castor Co
665 Great Southern Road, Penrose
Auckland 1061, New Zealand
(64) 9 580 3038

See www.recalls.govt.nz for
other New Zealand consumer product recalls